Fax:23698454 Apr 4 '05 17:32 P.07/1

Customer No.: 31561 Application No.: 10/604,981 Docket No.: 9892-US-PA

REMARKS

Present Status of the Application

The drawings are objected because the drawings do not show every feature of the invention specified in the claims. The Office Action rejected presently-pending claims 1, 3, 4, 10. Specifically, the Office Action rejected claims 1, 3, 4, 10 under 35 U.S.C. 112 as being indefinite for failing to particular point out and distinctly claim the subject matter which applicant regards as the invention. The Office Action rejected claims 1, 3, 4, 10 under 35 U.S.C. 102(b), as being anticipated by Kim et al. (U.S. 6,429,909). Applicants have amended claim 1 and cancelled claim 10. After entry of the foregoing amendments, claims 1, 3, 4 remain pending in the present application, and reconsideration of those claims is respectfully requested.

Discussion of Office Action Objections and Rejections

In claim 1, "the pixel electrode, the data line and the source/drain are electrically connected together" is amended as --one of the source and the drain is electrically connected to the data line and the other of the source and the drain, not connected to the data line, is electrically connected to the pixel electrode— to overcome the objection of the drawings and overcome the rejection of claim 1 under 35 U.S.C.112.

BEST AVAILABLE COPY

Page 6

Apr 4'05 17:40

P. 08/10

Fax:23698454

Customer No.: 31561 Application No.: 10/604,981 Docket No.: 9892-US-PA

The limitations added in claim 1 are shown in Fig. 4 and described in paragraph [0029] of the specification.

Applicants respectfully traverse the 102(b) rejection of claims 1, 3, 4 because Kim (U.S. 6,429,909) does not teach every element recited in these claims.

In order to properly anticipate Applicants' claimed invention under 35 U.S.C 102, each and every element of claim in issue must be found, "either expressly or inherently described, in a single prior art reference". "The identical invention must be shown in as complete details as is contained in the claim. Richardson v. Suzuki Motor Co., 868 F. 2d 1226, 1236, 9 USPQ2d 1913, 1920 (Fed. Cir. 1989)." See M.P.E.P. 2131, 8th ed., 2001.

The present invention is in general related a pixel structure as claim 1 recites:

Claim 1. A pixel structure formed on a transparent substrate, comprising:

a first conductive layer formed on a transparent substrate, wherein the first
conductive layer comprises a scan line and a gate, the gate and the scan line being electrically

a first dielectric layer formed on the transparent substrate covering the first conductive layer;

connected together;

a channel layer formed over the first dielectric layer above the gate;

a second conductive layer formed over the first dielectric layer, wherein the second conductive layer comprises a data line, a source and a drain such that the gate, the channel layer, the source and the drain together constitute a thin film transistor, and the data line in the area above the scan line branches out into a plurality of subsidiary lines, wherein one of the subsidiary lines short-circuited is cut;

a second dielectric layer formed on the first dielectric layer covering the second conductive layer, wherein a pair of repair openings is formed in the second dielectric layer to expose the cut subsidiary line;

a pixel electrode formed over the second dielectric layer, wherein one of the source and the drain is electrically connected to the data line and the other of the source and the drain, not connected to the data line, is electrically connected to the pixel electrode; and

Fax: 23698454 Apr 4 '05 17:43 P.09/10

Customer No.: 31561 Application No.: 10/604,981

Docket No.: 9892-US-PA

a thin metallic layer formed on the second dielectric layer between the repair openings and inside the repair openings so that the thin metallic layer is electrically connected

to the data line.

Kim does not teach the features of "one of the subsidiary lines short-circuited is cut" and

"a thin metallic layer is formed on the second dielectric layer between the repair openings and

inside the repair openings so that the thin metallic layer is electrically connected to the data line".

In Kim's reference, the structure, as shown in Fig. 17A and Fih 17B, includes a gate line 100,

repair lines 110, 120, a channel layer 300, a source S, a drain D, a data line 400 and a pixel

electrode 600. The repair lines 110, 120 are formed under the data line 400, and the data line 400

is divided into two branch lines 410, 420 being connected to the repair lines 110, 120 through the

contact hole C5, C6. In addition, the pixel electrode 600 contacts the drain D through the contact

hole C4.

Kim fails to teach that one of the subsidiary lines short-circuited is cut and the metallic

layer is formed on the second dielectric layer between the repair openings and inside the repair.

openings so that the thin metallic layer is electrically connected to the data line. Therefore, Kimi

does not teach every element recited in claim 1.

For at least the foregoing reasons, Applicant respectfully submits that independent claim

1 patently define over the prior art references, and should be allowed. For at least the same

reasons, dependent claims 3-4 patently define over the prior art as well.

Page 8

Apr 4 '05 17:45 P.10/10

Customer No.: 31561 Application No.: 10/604,981 Docket No.: 9892-US-PA

CONCLUSION

Fax:23698454

For at least the foregoing reasons, it is believed that the pending claims 1, 3-4 are in proper condition for allowance. If the Examiner believes that a telephone conference would expedite the examination of the above-identified patent application, the Examiner is invited to call the undersigned.

Date: April 4, 2005

Belinda Lee

Registration No.: 46,863

Respectfully submitted,

Jianq Chyun Intellectual Property Office 7th Floor-1, No. 100 Roosevelt Road, Section 2 Taipei, 100 Taiwan

Tel: 011-886-2-2369-2800 Fax: 011-886-2-2369-7233

Email: belinda@jcipgroup.com.tw Usa@icipgroup.com.tw

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS

IMAGE CUT OFF AT TOP, BOTTOM OR SIDES

FADED TEXT OR DRAWING

BLURRED OR ILLEGIBLE TEXT OR DRAWING

SKEWED/SLANTED IMAGES

COLOR OR BLACK AND WHITE PHOTOGRAPHS

GRAY SCALE DOCUMENTS

LINES OR MARKS ON ORIGINAL DOCUMENT

REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER:

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.